

|  |                         |           |                                 |                           |                             |
|--|-------------------------|-----------|---------------------------------|---------------------------|-----------------------------|
| <b>Garmong Construction Services</b>   |                         |           |                                 |                           |                             |
| <i>EMPLOYEE SAFETY POLICY HANDBOOK – Barricades, Caution Tape, &amp; Warning Signs</i> |                         |           |                                 |                           |                             |
| <b>Last Revised:</b>   | <b>January 24, 2012</b> | <b>By</b> | <b>Douglas Mahurin, MS, CSP</b> | <b>This Copy Printed:</b> | <b>1/24/2012 5:15:00 PM</b> |

## **BARRICADES, CAUTION TAPE, & WARINING SIGNS**

Signs, tags, banner tape, and color codes will be used on construction sites to warn employees of hazardous conditions and help them in case of an emergency.

Danger Tape is **RED**.

Danger tape shall be used where there is immediate danger or risk exposure.

Unauthorized personnel **shall not** enter or pass through an area demarked with red banner tape until given specific instruction that it is safe to do so by the responsible person / crew who established the banner.

Examples are: DANGER – HIGH VOLTAGE, DANGER – KEEP OUT, DANGER – NO SMOKING. Red is also the color that identifies fire protection equipment and apparatus, safety cans, fire extinguishers and alarms.

Caution Tape is **YELLOW**.

Caution tape shall be used as a warning to personnel of a potential or known hazard.

Personnel may enter or pass through a yellow caution banner after reading the banner tape identification tag affixed to the tape and making a careful evaluation of the hazards, determining it is safe to proceed while taking precautions as required in order not to be exposed to the identified hazard.

Examples: CAUTION – WATCH YOUR STEP, CAUTION – LIVE POWER SUPPLY, CAUTION – EYE PROTECTION REQUIRED.

**ORANGE** is the color used to identify dangerous machine parts. These are locations that can cause major lacerations, crushing injuries or electrical shock. For example, gears, pulleys and rollers may be marked with this color.

Never leave an area with an opening someone could fall into unprotected. Use Barricades to Protect Others from Falling in and Always Post Warning Signs or Banner Tape.